

ಕರ್ನಾಟಕ ಸರ್ಕಾರ  
(ಜಲ ಸಂಪನ್ಮೂಲ ಇಲಾಖೆ)

ಅತಿವೃಷ್ಟಿ/ ಪ್ರವಾಹದಡಿಯಲ್ಲಿ ಅಡಿಯಲ್ಲಿ ಕೈಗೆತ್ತಿಕೊಂಡ ವಿವಿಧ ಇಲಾಖಾ  
ಕಾಮಗಾರಿಗಳ ವಿವರಗಳ ಮಾಹಿತಿ


ದಿನಾಂಕ: 02-01-2010

ಅಧೀಕ್ಷಕ ಅಭಿಯಂತರವರ ಕಛೇರಿ  
ತುಂಗಭದ್ರಾ ಕಾಲುವೆ ನಿರ್ಮಾಣ ವೃತ್ತ  
ಯರಮರಸಿ ಶಿಬಿರ, ರಾಯಚೂರು

ಅತಿವ್ರಷ್ಟಿ/ ಪ್ರವಾಹದಡಿಯಲ್ಲಿ ಅಡಿಯಲ್ಲಿ ಕೈಗೆತ್ತಿಕೊಂಡ ವಿವಿಧ ಇಲಾಖಾ ಕಾಮಗಾರಿಗಳ ವಿವರಗಳ ಮಾಹಿತಿ

ಮೊತ್ತ : ಲಕ್ಷಗಳಲ್ಲಿ

ಕ್ರ.ಸಂ	ತಾಲೂಕು	ಕ್ರಿಯಾ ಯೋಜನೆ ಪ್ರಕಾರ		ಆಡಳಿತಾತ್ಮಕ		ಪ್ರಾರಂಭವಾದ ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ	ಪ್ರಾರಂಭವಾಗಿ ಬೇಕಾದ ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ	ಮುಕ್ತಾಯ ಗೊಂಡ ಕಾಮಗಾರಿ ಗಳ ಸಂಖ್ಯೆ	ಮುಕ್ತಾಯ ಹಂತದಲ್ಲಿರು ವ ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ	ಅನುಷ್ಠಾನಾಧಿಕಾರಿಗಳವರಿಗೆ		ಖರ್ಚುಆದ ಅನುದಾನ	ಬಾಕಿ ಉಳಿದ ಅನುದ ಾನ	ಷರಾ
		ಕಾಮಗಾರಿ ಸಂಖ್ಯೆ	ಅಂದಾಜು ಮೊತ್ತ	ಕಾಮಗಾರಿ ಸಂಖ್ಯೆ	ಅಂದಾಜು ಮೊತ್ತ					ನಿಗದಿ ಪಡಿಸಿದ ಅನುದಾನ	ಬಿಡುಗಡೆ ಮಾಡಿದ ಅನುದಾನ			
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
1	ಸಿಮಧನೂರು	75	125.00	75	125.00	75		75		125	125			ಸಿಂಧನೂರು ಮಾಗ
2	ಮಾನವಿ	125	125.00	122	121.00	125		87	38	125	125			ಸಿರವಾರ ವಿಭಾಗ
3	ರಾಯಚೂರು	27	70.80	27	70.80	27		12	15					
4	ಮಾನವಿ	18	60.20	18	60.20	18		5	13	150	150			ಯರಮರಸ ವಿಭಾಗ
5	ದೇವದುರ್ಗ	5	19.00	5	19.00	5		3	2					
		<b>250</b>	<b>400.00</b>	<b>247</b>	<b>396.00</b>	<b>250</b>		<b>182</b>	<b>68</b>	<b>400</b>	<b>400</b>			

  
 ಅಧೀಕ್ಷಕ ಅಭಿಯಂತರು (ಜ.ಸ.ಇ) ಶಿವಮೊಗ್ಗ  
 ಶುಂಗಭದ್ರ ಕಾಲುವೆ ನಿರ್ಮಾಣ ವ್ಯಕ್ತ,  
 ಯರಮರಸ (ಶಿಬಿರ) 58-134.

ಅತಿವೃಷ್ಟಿ/ ಪ್ರವಾಹದಡಿಯಲ್ಲಿ ಅಡಿಯಲ್ಲಿ ಕೈಗೆತ್ತಿಕೊಂಡ ವಿವಿಧ ಇಲಾಖಾ ಕಾಮಗಾರಿಗಳ ವಿವರಗಳ ಮಾಹಿತಿ

ತಾಲೂಕು:

ಇಲಾಖೆ: ಬಲ ಸಂಪನ್ಮೂಲ ಇಲಾಖೆ ( No 3 Canal Division, Sindhanoor)

ಕ್ರ.ಸಂ	ಕಾಮಗಾರಿ ಹೆಸರು(ಸಿಂಧನೂರು)	ಗ್ರಾಮ	ಕ್ರಿಯಾ ಯೋಜನೆ ಪ್ರಕಾರ		ಅಡಳಿತಾತ್ಮಕ ಅನುಮೋದನೆ ನೀಡಿದ ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ		ಪ್ರಾರಂಭವಾದ ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ	ಪ್ರಾರಂಭವಾಗ ಬೇಕಾದ ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ	ಮುಕ್ತಾಯ ಗೊಂಡ ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ	ಮುಕ್ತಾಯ ಹಂತದಲ್ಲಿರುವ ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ	ಅನುಷ್ಠಾನಾಧಿಕಾರಿಗಳವರಿಗೆ		ಖರ್ಚು ಅದ ಅನುದಾನ	ಬಾಕಿ ಉಳಿದ ಅನುದಾನ	ಷರಾ
			ಕಾಮಗಾರಿ ಸಂಖ್ಯೆ	ಅಂದಾಜು ಮೊತ್ತ	ಕಾಮಗಾರಿ ಸಂಖ್ಯೆ	ಅಂದಾಜು ಮೊತ್ತ					ನಿಗದಿ ಪಡಿಸಿದ ಅನುದಾನ	ಬಿಡುಗಡೆ ಮಾಡಿದ ಅನುದಾನ			
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
1	Removal of silt from ch. 5.00 to 60.00 of D/40 of TLBC.	1	0.90	1	0.90	1	--	1	--	125	Nil	--	--		
2	Improvements to SR from Ch. 0.00 to 50.00 of D/41 of TLBC.	1	3.00	1	3.00	1	--	1	--			--	--		
3	Improvements to SR from Ch. 0.00 to 86.00 of D/42 of TLBC.	1	5.00	1	5.00	1	--	1	--			--	--		
4	Improvements to hard passage near Killarhatti village of KNP service road.	1	2.50	1	2.50	1	--	1	--			--	--		
5	Fillup the rain cuts with murrum and Improvements to Bund of KNP dam.	1	1.50	1	1.50	1	--	1	--			--	--		
6	Re-restoration of slope lining L/s of tail end Distributory of KNP.	1	2.50	1	2.50	1	--	1	--			--	--		
7	Re-restoration of slope lining R/s of tail end Distributory of KNP.	1	3.00	1	3.00	1	--	1	--			--	--		
8	Improvements to SR L/s & R/s tail end Distributory of KNP	1	1.50	1	1.50	1	--	1	--			--	--		
9	Repairs to SR from ch. 538 to 591 of D	1	0.25	1	0.25	1	--	1	--			--	--		

ಅತಿವೃಷ್ಟಿ/ ಪ್ರವಾಹದಡಿಯಲ್ಲಿ ಅಡಿಯಲ್ಲಿ ಕೈಗೆತ್ತಿಕೊಂಡ ವಿವಿಧ ಇಲಾಖಾ ಕಾಮಗಾರಿಗಳ ವಿವರಗಳ ಮಾಹಿತಿ

ತಾಲೂಕು:

ಇಲಾಖೆ: ಜಲ ಸಂಪನ್ಮೂಲ ಇಲಾಖೆ ( No 3 Canal Division, Sindhanoor)

ಕ್ರ.ಸಂ	ಕಾಮಗಾರಿ ಹೆಸರು(ಸಿಂಧನೂರು)	ಗ್ರಾಮ	ಕ್ರಿಯಾ ಯೋಜನೆ ಪ್ರಕಾರ		ಆಡಳಿತಾತ್ಮಕ ಅನುಮೋದನೆ ನೀಡಿದ ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ		ಪ್ರಾರಂಭವಾದ ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ	ಪ್ರಾರಂಭವಾಗ ಬೇಕಾದ ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ	ಮುಕ್ತಾಯ ಗೊಂಡ ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ	ಮುಕ್ತಾಯ ಹಂತದಲ್ಲಿರುವ ಕಾಮಗಾರಿಗಳ ಸಂಖ್ಯೆ	ಅನುಷ್ಠಾನಾಧಿಕಾರಿಗಳವರಿಗೆ		ಖರ್ಚುಅದ ಅನುದಾನ	ಬಾಕಿ ಉಳಿದ ಅನುದಾನ	ಷರಾ
			ಕಾಮಗಾರಿ ಸಂಖ್ಯೆ	ಅಂದಾಜು ಮೊತ್ತ	ಕಾಮಗಾರಿ ಸಂಖ್ಯೆ	ಅಂದಾಜು ಮೊತ್ತ					ನಿಗದಿ ಪಡಿಸಿದ ಅನುದಾನ	ಬಿಡುಗಡೆ ಮಾಡಿದ ಅನುದಾನ			
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
1	Removal of silt from ch. 5.00 to 60.00 of D/40 of TLBC.	1	0.90	1	0.90	1	--	1	--	125	Nil	--	--		
2	Improvements to SR from Ch. 0.00 to 50.00 of D/41 of TLBC.	1	3.00	1	3.00	1	--	1	--			--	--		
3	Improvements to SR from Ch. 0.00 to 86.00 of D/42 of TLBC.	1	5.00	1	5.00	1	--	1	--			--	--		
4	Improvements to hard passage near Killarhatti village of KNP service road.	1	2.50	1	2.50	1	--	1	--			--	--		
5	Fillup the rain cuts with murrum and Improvements to Bund of KNP dam.	1	1.50	1	1.50	1	--	1	--			--	--		
6	Re-restoration of slope lining L/s of tail end Distributory of KNP.	1	2.50	1	2.50	1	--	1	--			--	--		
7	Re-restoration of slope lining R/s of tail end Distributory of KNP.	1	3.00	1	3.00	1	--	1	--			--	--		
8	Improvements to SR L/s & R/s tail end Distributory of KNP	1	1.50	1	1.50	1	--	1	--			--	--		
9	Repairs to SR from ch. 538 to 591 of D	1	0.25	1	0.25	1	--	1	--			--	--		

10	Scour filling and raising of Bank from ch 800 to 826 L/s of D-54 Iind Reach.	1	0.40	1	0.40	1	--	1	--			--	--		
11	Raising of Bank L/s From Ch 937 to 947 of D-54 Iind Reach.	1	0.80	1	0.80	1	--	1	--			--	--		
12	Repair to PO @ Ch 1006 L/s and raising of Bank from Ch 1075 to 1081 of D-54 Iind Reach.	1	0.80	1	0.80	1	--	1	--			--	--		
13	Raising of Bank from ch 1268 to 1275 and repairs to PO @ ch 1239 L/s ,1189 L/s of D-54 Iind Reach.	1	0.50	1	0.50	1	--	1	--			--	--		
14	Removal of silt from ch. 1192.00 to 1356.00 of D/54 II reach of TLBC.	1	2.50	1	2.50	1	--	1	--			--	--		
15	Removal of silt and scour filling of SD/19L & 20L of D/54 II reach of TLBC.	1	2.00	1	2.00	1	--	1	--			--	--		
16	Removal of silt and scour filling of SD/25L of D/54 II reach of TLBC.	1	0.50	1	0.50	1	--	1	--			--	--		
17	Raising of Bank @ Ch (L/s) 403 to 408 of 9R WBB of D-54 II nd Reach.	1	1.50	1	1.50	1	--	1	--			--	--		
18	Raising of Bank @ Ch 540 to 545 of 9R WBB of D-54 II nd Reach.	1	2.00	1	2.00	1	--	1	--			--	--		
19	Construction of Escape @ Ch 581 of 9R WBB of D-54 II nd Reach.	1	3.00	1	3.00	1	--	1	--			--	--		
20	Raising of Bank @ Ch R/s 122 to 149 of 9R ABB (MSB) of D54 II nd Reach.	1	3.00	1	3.00	1	--	1	--			--	--		
21	Raising of Bank @ Ch 240 to 250 and 272 to 278 ( Scour filling ) of 9R ABB of D-54 II nd Reach.	1	3.00	1	3.00	1	--	1	--			--	--		
22	Repairs to Head wall and Scour filling of 9R/A of D-54 II nd Reach.	1	0.45	1	0.45	1	--	1	--			--	--		
23	Repairs to Rear Head Wall and Scour filling @ Ch 423 of 9 R WBB of D-54 II nd Reach.	1	0.25	1	0.25	1	--	1	--			--	--		

24	Construction of Guide wall with pitching in halla portion from Km 0.115 to 0.130 of Gorebal pickup feeder Channel	1	2.00	1	2.00	1	--	1	--			--	--		
25	Construction of Guide wall with pitching in halla portion from Km 0.130 to 0.145 of Gorebal pickup feeder Channel	1	2.00	1	2.00	1	--	1	--			--	--		
26	Construction of Guide wall with pitching in halla portion from Km 0.145 to 0.160 of Gorebal pickup feeder Channel	1	2.00	1	2.00	1	--	1	--			--	--		
27	Construction of Guide wall with pitching in halla portion from Km 0.160 to 0.175 of Gorebal pickup feeder Channel	1	2.00	1	2.00	1	--	1	--			--	--		
28	Re-construction of Super passage at Km 0.36 of Gorebal pickup feeder Channel	1	2.00	1	2.00	1	--	1	--			--	--		
29	Removal of Silt and slipped earth from Km 0.00 to 1.00 of Gorebal pickup feeder Channel	1	2.00	1	2.00	1	--	1	--			--	--		
30	Removal of Silt and slipped earth from Km 4.56 to 5.00 of Gorebal pickup feeder Channel	1	1.00	1	1.00	1	--	1	--			--	--		
31	Removal of Silt and slipped earth from Km 5.00 to 6.00 of Gorebal pickup feeder Channel	1	1.50	1	1.50	1	--	1	--			--	--		
32	Removal of Silt and slipped earth from Km 6.00 to 7.00 of Gorebal pickup feeder Channel	1	1.50	1	1.50	1	--	1	--			--	--		
33	Removal of Silt and slipped earth from Km 7.00 to 8.00 of Gorebal pickup feeder Channel	1	1.50	1	1.50	1	--	1	--			--	--		
34	Re-construction of C.T.,C at Km 7.55 of Gorebal pickup feeder Channel.	1	1.50	1	1.50	1	--	1	--			--	--		

35	Re-construction of C.T.,C at Km 7.80 of Gorebal pickup feeder Channel.	1	1.50	1	1.50	1	--	1	--			--	--		
36	Raising of R/s Canal Embankment from Ch 840 to 850 and Scour Filling at Ch 839.00 of D-36	1	1.50	1	1.50	1	--	1	--			--	--		
37	Repairs to C.D's at Ch 12.50,37.50 of SD-36/6 of D-36	1	1.50	1	1.50	1	--	1	--			--	--		
38	Repairs to C.D's at Ch 71 ,102 and Scour fill of D-36	1	1.50	1	1.50	1	--	1	--			--	--		
39	Repairs to Drop at ch 830.00 of D-36	1	1.00	1	1.00	1	--	1	--			--	--		
40	Raising of R/s Canal Embankment from Ch 717 to 719 and Scour Filling of D-36	1	1.00	1	1.00	1	--	1	--			--	--		
41	Raising of R/s Canal Embankment from Ch 728to 735 of D-36	1	1.00	1	1.00	1	--	1	--			--	--		
42	Repairs to Drop Notch Wall at ch 671 of D-36	1	0.10	1	0.10	1	--	1	--			--	--		
43	Scour Filling at ch.679 of D-36	1	0.20	1	0.20	1	--	1	--			--	--		
44	Repairs to drainage at ID camp Sindhanur.	1	1.50	1	1.50	1	--	1	--			--	--		
45	Repairs to permnent RCC building @ ID camp in Sindhanur A1, A2, A3, A4, A5, A6	1	2.00	1	2.00	1	--	1	--			--	--		
46	Improvements to iternal road @ ID camp Sindhanur	1	1.50	1	1.50	1	--	1	--			--	--		
47	Repairs to SR in M/60 of TLBC	1	0.50	1	0.50	1	--	1	--			--	--		
48	Repairs to SR in M/61 of TLBC	1	0.50	1	0.50	1	--	1	--			--	--		
49	Repairs to SR in M/62 of TLBC	1	0.50	1	0.50	1	--	1	--			--	--		
50	Repairs to SR in M/63 of TLBC	1	0.50	1	0.50	1	--	1	--			--	--		
51	Repairs to SR in M/64 of TLBC	1	0.50	1	0.50	1	--	1	--			--	--		
52	Repairs to SR in M/65 of TLBC	1	0.50	1	0.50	1	--	1	--			--	--		
53	Repairs to SR in M/66 of TLBC	1	0.50	1	0.50	1	--	1	--			--	--		
54	Repairs to SR in M/67 of TLBC	1	0.50	1	0.50	1	--	1	--			--	--		
55	Repairs to SR in M/68 of TLBC	1	0.50	1	0.50	1	--	1	--			--	--		
56	Repairs to SR in M/69 of TLBC	1	0.50	1	0.50	1	--	1	--			--	--		

57	Repairs to rear slope embankment approach of aqueduct @ ch. 3233 L/s & R/s in M/61 of TLBC	1	3.00	1	3.00	1	--	1								
58	Repairs to rear slope approaches of aqueduct @ ch. 3614 Regulator cum cart bridge @ ch. 3627 in M/68 of TLBC.	1	4.00	1	4.00	1	--	1								
59	Repairs to rain damaged embankment from ch. 322 to 324.50 R/s of D/54 I reach of TLBC	1	1.50	1	1.50	1	--	1								
60	Repairs to rain damaged embankment from ch. 356 to 358 R/s of D/54 I reach of TLBC	1	0.40	1	0.40	1	--	1								
61	Repairs to rain damaged embankment from ch. 450 to 451 L/s of D/54 I reach of TLBC	1	0.45	1	0.45	1	--	1								
62	Removal of debris from Km. 0.00 to 1.00 of SD/2L of D/54 I reach	1	2.50	1	2.50	1	--	1								
63	Removal of debris from Km. 0.00 to 4.00 of SD/3R of D/54 I reach	1	4.00	1	4.00	1	--	1								
64	Removal of debris from Km. 0.00 to Teail end of SD/4R of D/54 I reach	1	3.00	1	3.00	1	--	1								
65	Removal of debris from Km. 0.00 to Teail end of SD/7R of D/54 I reach	1	5.00	1	5.00	1	--	1								
66	Raising of embankment from Km. 0.50 to 1.50 (In selected reaches) of D/55	1	2.00	1	2.00	1	--	1								
67	Raising of embankment from Km. 2.00 to 3.00 (In selected reaches) of D/55	1	2.00	1	2.00	1	--	1								
68	Raising of embankment from Km. 3.00 to 4.00 (In selected reaches) of D/55	1	2.00	1	2.00	1	--	1								





21	Providing scour filling & construction of G.W. of the approaches D/82/1 of D/82 of TLBC	Bagalawad	1	1.00		1.00	1		1								
22	Scour filling on SR Side & IP Side at Disty 82 of TLBC	Ballatagi	1	0.90		0.90	1		1								
23	Scour filling and rain cuts filling in Disty 84 of TLBC	Ballatagi	1	0.50		0.50	1		1								
24	Scour filling and rasing of bank in between in km 1.50 to 3 Disty 84 of TLBC	Mallat	1	1.50		1.50	1		1								
25	filling of rain cuts of SR in between km 1 to 2 of D/84 Of TLBC	Mallat	1	1.00		1.00	1		1								
26	Scour filling on SR in Disty 87 of TLBC	Navalkal	1	0.80		0.80	1		1								
27	Filling of Rain cuts on SR of Disty 90 of TLBC	Sirwar	1	1.00		1.00	1		1								
28	Filling of Rain cuts on SR of Disty 91 of TLBC	Sirwar	1	0.50		0.50	1		1								
29	Filling of Rain cuts on SR in between km 0 to 3 of Disty 92 of TLBC	Sirwar	1	1.50		1.50	1		1								
30	Filling of Rain cuts on SR in between km 6 to 10 of Disty 92 of TLBC	Ganadinni	1	2.00		2.00	1		1								
31	Rain damages to A type Quarters building 4 No.s	Sirwar	1	2.00		-	-										Estimate Not submitted
32	Rain damages @ pipe culvert in km 0.90 and providing wearing coat low casway between km 2 to 3 of Sirwar to Jalpur avacut road	Sirwar	1	1.00		1.00	1		1								
33	Flood damage low level casway at km 2 of Ballatgi to Bagalwad road	Ballatagi	1	1.00		1.00	1		1								
34	Rain damages @ pipe culvert in km 4 of Ballatgi to Bagalwad Ayacut road	Ballatagi	1	1.00		1.00	1		1								
35	Rain damages in 15th km of Bagalwad to H.B Dinni Devatakakal to RL Road	Bagalawad	1	1.00		1.00	1										
36	Rain damages to C.D work at 2 nd km of R.L Road to Kadadinni Ayacut road	Chagabavi	1	0.90		0.90	1										
37	Raind damages to S M Road to Lakmadinni Ayacut road	Chagabavi	1	0.90		0.90	1			1							
38	Raind damages to S M Road to Sanna Hosura Ayacut road	Chagabavi	1	0.50		0.50	1			1							
39	Flood rain damage to super passage at 6 th km of D/79 of TLBC	Bagalawad	1	6.00		6.00	1			1							
40	Flood rain damage to Canal service road of SD 92/1 from km 0 to 2 of D/92	Attanur	1	0.90		0.90	1			1							

41	Flood rain damage to Canal service road of SD 92/1 from km 2 to 4 of D/92	Ganadinni	1	0.90	0.90	1			1					
42	Flood rain damage to Canal service road of SD 92/2 from km 0 to 2 of D/92	Ganadinni	1	0.80	0.80	1			1					
43	Flood rain damage to super passage at 3 th km of D/81 of TLBC	Bagalawad	1	0.90	0.90	1			1					
44	Rain cuts occurred to service road in ch 4306 in km 128 Mile 81& km 121 of TLBC	Basapur	1	0.5	0.5	1		1						
45	Rain cuts occurred to I.P. side at ch 4348 in km 129 mile 81 of TLBC	Basapur	1	0.50	0.50	1			1					
46	Rain cuts occurred to service road at ch 4410 in km 131 mile 83 of TLBC	Basapur	1	0.50	0.50	1			1					
47	Rain cuts occurred to Inspection path at ch 4431 in km 132 mile 83 of TLBC	Basapur	1	0.50	0.50	1			1					
48	Rain damages caused to Inpsection path in km 1 of Disty. 65 of TLBC	Halapur	1	2.00	2.00	1		1						
49	Rain damages caused to Inpsection path in km 2 of Disty. 65 of TLBC	Halapur	1	1.00	1.00	1			1					
50	Rain damages caused to SR in km 3 of Disty. 65 of TLBC	Edaldinni	1	1.00	1.00	1			1					
51	Rain damages caused to low level cause way in km 3 of Disty 65 of TLBC	Edaldinni	1	3.00	3.00	1		1						
52	Rain damages to Inpsection path in km 3 of Diaty 65 of TLBC	Gogibal	1	0.50	0.50	1			1					
53	Rain damages casued to canal & service road to in damaged reaches from 1 to 4 km of D/71	Chikadinni	1	1.00	1.00	1			1					
54	Rain damages casued to canal & service road to in damaged reaches from 1 to 6 km of D/73	Ganganagr	1	0.50	0.50	1			1					
55	Rain damages casued to canal & service road to in damaged reaches in D/74	Narayan N	1	0.50	0.50	1			1					
56	Rain damages casued to canal & service road to in damaged reaches from ch 302 to 364 D/65	Torndinni	1	0.70	0.70	1			1					
57	Rain damage casued to canal & service road to in damaged reaches from km 5 to 6 D/69	Malldagudda	1	0.30	0.30	1			1					
58	Rain damages casued to CD work and road from Torndinni to Malladgudda road	Hiredinni	1	1.00	1.00	1			1					
59	Rain damages casued to road from Hiredinni to Markamdinni via Sunknur road		1	0.50	0.50	1			1					

60	Repairs to SWF at ch 2 of D/89	Kadadinni	1	0.75		0.75	1			1					
61	Providing protective work to RCC drop at ch 54 of D 89 ring bund	Kadadinni	1	0.75		0.75	1			1					
62	Repairs to Spcum CB at ch 428 of D/89	Chagabavi	1	0.60		0.60	1			1					
63	Repairs to approaches of CB at ch 392 of D/89	Chagabavi	1	0.90		0.90	1			1					
64	Repairs to drop at ch 470 D/89	Harvi	1	0.60		0.60	1			1					
65	Scour filling to( approaches) drop U/S of drop at ch 690 of D/89	N.manvi	1	0.60		0.60	1			1					
66	Scour filling behind P.O at ch 510 R/S of D/89	Betadur	1	0.55		0.55	1			1					
67	Protective works to SP with SR bonga filling at ch 802 of D/89	Betadur	1	0.95		0.95	1			1					
68	Repairs to CD at ch 241 of D/89	Chagabavi	1	0.60		0.60	1			1					
69	Scour filling to SR at ch 837(PO at ch 837 L/S) of D/89	Betadur	1	0.50		0.50	1			1					
70	filling rain cut at ch 948 of D/89	Betadur	1	0.50		0.50	1			1					
71	Filling rain cutt with protective works to inlet at ch 12 and ch 27 L/S of D/85	N.Hosur	1	0.95		0.95	1			1					
72	Filling rain cutt with protection work to drop at ch 90 of D/85	N.Hosur	1	0.90		0.90	1			1					
73	Raising of bund with rain cut filling from ch 110 to 120 L/S of D/85	N.Hosur	1	0.95		0.95	1			1					
74	Rain cut filling with protective works to drops at ch 120 R/S and L/S of D/85	N.Hosur	1	0.95		0.95	1			1					
75	Scour filling with protective works to drop at ch 402 of D/85	Ballatagi	1	1.50		1.50	1			1					
76	Rain cutt filling with scour filling at ch 272 and 276 R/S of D/85	Ballatagi	1	1.95		1.95	1			1					
77	scour filling and bonga filling at ch 634 of D/85	Manvi	1	0.75		0.75	1		1						
78	Raising of L/S bank and scour filling and improvements to SR at ch 741 of D/85	Manvi	1	0.95		0.95	1			1					
79	Raising of bank and scour filling and improvements to SR at ch 741 of D/85	Manvi	1	0.60		0.60	1		1						
80	Filling rain cuts and improvements to SR from ch 832 to 836 of D/85	Rabnkai	1	0.75		0.75	1			1					
81	Filling rain cutts and improvements to SR in Mnavi town of D/85	Manvi	1	1.95		1.95	1			1					
82	Improvements to AR from Sunkeshwar to Sadapur km 2.5 to 3 (flood damage portion)	Sunkeshwar	1	3.00		3.00	1			1					

83	Repairs to damaged CTC and LL casuse way in AR from RG road Ponnur via Sadapur	Sadapur	1	2.00		2.00	1			1					
84	Repairs to LL cause way and CD works in AR from RG road to Seekla Bapur on Korvi	Seekal	1	2.00		2.00	1			1					
85	Repairs to flood damaged gauge room at Nirmanvi ID camp	N Manvi	1	1.95						1					Estimate Not submitted
86	Improvements to camp road at ID camp Manvi	Manvi	1	1.65		1.65				1					Estimate Not submitted
87	Rain cuts occurred to service road in ch 4671 to 4689 in km 141 of TLBC	Bagalawad	1	0.50		0.50	1		1						
88	Rain cuts occurred to service road in ch 4689 to 4696 in km 141 of TLBC	Bagalawad	1	0.50		0.50	1		1						
89	Rain cuts occurred to service road in ch 4754 to 4770 in km 142 of TLBC	Bagalawad	1	1.00		1.00	1		1						
90	Rain damaged caused to CC lining in km 0.60 of Disty. 76 of TLBC	Bagalawad	1	1.50		1.50	1		1						
91	Rain damaged caused to Head sluice D/S SD 76/1 of Disty. 76 of TLBC	Bagalawad	1	0.25		0.25	1		1						
92	Rain damaged caused to Head sluice D/S SD 76/2 of Disty. 76 of TLBC	Bagalawad	1	0.25		0.25	1		1						
93	Rain damaged caused to CC lining at ch 218 of Disty. 76 of TLBC	Bagalawad	1	0.50		0.50	1		1						
94	Rain damage to drop at ch 415 of Disty 76 of TLBC	Nakundi	1	1.00		1.00	1		1						
95	Rain damage to drop at ch 446 of Disty 76 of TLBC	Nakundi	1	1.00		1.00	1		1						
96	Rain damage to drop at ch 493 of Disty 76 of TLBC	Hirekotnekal	1	1.00		1.00	1		1						
97	Rain damage to drop at ch 545 of Disty 76 of TLBC	Hirekotnekal	1	1.00		1.00	1		1						
98	Rain damage to drop at ch 546 of Disty 76 of TLBC	Hirekotnekal	1	1.00		1.00	1		1						
99	Rain damage to drop at ch 547 of Disty 76 of TLBC	Hirekotnekal	1	1.00		1.00	1		1						
100	Rain damage caused scour at ch 712 L/S of Disty 76 of TLBC	Hirekotnekal	1	1.00		1.00	1		1						

101	Rain damage caused scour at ch 745 L/Sof Disty 76 of TLBC	Hirekotnekal	1	0.75	0.75	1	1								
102	Rain damage caused scour at ch 819 L/S of Disty 76 of TLBC	Hirekotnekal	1	0.50	0.50	1	1								
103	Rain damage caused scour at ch 864 L/S of Disty 76 of TLBC	Hirekotnekal	1	0.60	0.60	1	1								
104	Rain damages to Office building of No 4 CSD Hirekotnekal	Hirekotnekal	1	1.00	1	1	1								
105	Rain damages to B-4 Quarters building of No 4 CSD Hirekotnekal	Hirekotnekal	1	0.50	0.50	1	1								
106	Rain damages to Eletrical serivce line of No 4 CSD Hirekotnekal camp	Hirekotnekal	1	1.00	1.00	1	1								
107	Rain daamaged to Hard pasage in km 1 of Bagalwad- Malladgudda AR	Bagalawad	1	2.00	2.00	1	1								
108	Rain daamaged to AR in km 0 to 6 of Malladgudda Bagalwad AR	Bagalawad	1	1.50	1.50	1	1								
109	Rain daamaged to CD in km 0 to 1.5 of Malladgudda Bagalwad AR	Bagalawad	1	0.75	0.75	1	1								
110	Rain daamaged to CD in km 1 to 3 of Malladgudda Bagalwad AR	Bagalawad	1	0.75	0.75	1	1								
111	Rain daamaged to CD in km 3 to 4.5 of Malladgudda Bagalwad AR	Bagalawad	1	0.75	0.75	1	1								
112	Rain daamaged to ARfrom Malladgudda Udbal in km 0 to 3 AR	Malladguda	1	1.00	1.00	1	1								
113	Rain daamaged to ARfrom Malladgudda Udbal in km 3 to 6 AR	Udbal	1	1.00	1.00	1	1								
114	Rain damage to Approches Karegudda road in km 0 to 1	karegudda	1	1.50	1.50	1	1								
115	Rain damage to Approches Nakundi road in km 0 to 3	Nakundi	1	0.50	0.50	1	1								
116	Rain damage to Approches Amaravati road in km 0 to 2	Amarviti	1	0.50	0.50	1	1								
117	Rain damage to side embankment in km 5 of SD 76/1 of D/76 &14R/S of SD 76/1 in km1	Malldagudda	1	1.50	1.50	1	1								
118	Rain damage to water courec to ch 19 R/S of SD 76/2 of TLBC in km 1 of SD762/ D/76	Donmard	1	1.50	1.50	1	1								
119	Rain damage to water courec to ch 93 L/S of SD 76/5 of D/76of TLBC	Jinur camp	1	1.40	1.40	1	1								
120	Rain damage to water courec to ch 135 L/S of SD 76/5 of D/76of TLBC	Potmal	1	1.20	1.20	1	1								
121	Rain damaged to CD strucutre in km 1 of SD 76/7 of D/76 of TLBC	Hirikotnekal	1	1.50	1.50	1	1								

122	Rain damages to P.O at ch 785 R/S of D/76 of TLBC	Hirikotnekal	1	0.75		0.75	1		1						
123	Rain damages to P.O at ch 803 R/S of D/76 SD of D/76 of TLBC	CKL	1	0.50		0.50	1		1						
124	Rain damages to P.O at ch 14 R/S of D/76/1 of D/76 in km 2 of TLBC	Malladguda	1	0.50		0.50	1		1						
125	Rain damages to road approaches in 0.50 to I. Seekal picup	Karvi sadpur	1	2.00		2.00	1		1						
<b>Total</b>			<b>125</b>	<b>124.6</b>	<b>122</b>	<b>120.6</b>	<b>122</b>	<b>0</b>	<b>87</b>	<b>38</b>					

ಅತಿವೃಷ್ಟಿ/ ಪ್ರವಾಹದಡಿಯಲ್ಲಿ ಅಡಿಯಲ್ಲಿ ಕೈಗೆತ್ತಿಕೊಂಡ ವಿವಿಧ ಇಲಾಖಾ ಕಾಮಗಾರಿಗಳ ವಿವರಗಳ ಮಾಹಿತಿ

ತಾಲೂಕು: ರಾಯಚೂರು ಇಲಾಖೆ: ಜಲ ಸಂಪನ್ಮೂಲ ಇಲಾಖೆ (No 5 Canal Division Yermarus camp )

1	Restoration to scour filling on S/R and IP saide at ch. 6482/mile 124 and ch. 6447/mile 124 and inlet damage ch. 6444/mile 123	1	3.50	1	3.50	1			1						
2	Breach filling and improvements of canal embankment at ch. 6871, 6895,6932,6953 in mile 131 to 132 of main canal of TLBC.	1	2.00	1	2.00	1		1							
3	Breach filling and improvements of canal embankment at ch.7010,7053 in mile 134 of TLBC.main canal	1	0.65	1	0.65	1		1							
4	Breach filling and improvements of canal embankment at ch. 7053, 7073,7093,7095 in mile 135 of TLBC Main canal	1	1.40	1	1.40	1		1							
5	Breach filling and improvements of canal embankment at ch. 7140, 7154,7166,7168 7181, 7492 in mile 136 and 139 of TLBC main canal	1	0.35	1	0.35	1		1							
6	Distributory -98 in Km. 0.00 to 5.00 Rising of bank and filling of rain cuts and scour filling	1	2.00	1	2.00	1		1							
7	Distributory -98 in sub distributory 98/2L Rising of bank and filling of rain cuts and scour filling	1	2.00	1	2.00	1			1						
8	Distributory -98/A in Km. 0.00 to 1.00 Rising of bank and filling of rain cuts and scour filling	1	0.50	1	0.50	1			1						
9	Distributory -98/B in sub distributory 98/3L Rising of bank and filling of rain cuts and scour filling	1	0.50	1	0.50	1			1						
10	Restoration to super passage inlet @ ch. 373.00in Disty-99	1	2.00	1	2.00	1		1							
11	Restoration to super passage inlet @ ch. 399.00in Disty-99	1	2.00	1	2.00	1		1							
12	Restoration to super passage inlet @ ch. 392.00 in Disty-99	1	2.00	1	2.00	1		1							

13	Providing ring bund at ch. 14 of waddigeri Basappa tank near Puchalladinni village.		1	2.50	1	2.50	1		1						
14	Breach filling in Waddigeri Basappa MI tank Gunjahalli near Puchalladhanni village.		1	8.00	1	8.00	1			1					
15	Brech filling an improvements to Udamgal tank at km 1.50 Ch 54 of tank		1	4.30	1	4.30	1			1					
16	Breach filling in Gadar basappa Goudar MI tank in Gadhar village		1	8.00	1	8.00	1			1					
17	Desilting of Vijayanagara Canal Km 9.00 to 12.00		1	1.00	1	1.00	1			1					
18	Restoration of Ayacut Road RG road to Hunasihahuda road		1	2.10	1	2.10	1		1						
19	Restoration of Ayacut Road from Matamari Railway station to Garaladinni		1	3.00	1	3.00	1			1					
20	Restoration of Aroli to Adavi Khanapur Ayacut Road		1	2.00	1	2.00	1			1					
21	Restoration of Ayacut road Mamadapur to RG road		1	4.00	1	4.00	1			1					
22	Restoration of Ashapur to Nelahal Aycut road		1	3.00	1	3.00	1			1					
23	Repair to hard passage at Km 2.00 and 4.6 of Manjarla Nagalapur road		1	3.00	1	3.00	1			1					
24	Repair and improvements to hard passage at Km 2.50 from Turukundona village across Alkur -Turukundona Ayacut road		1	0.50	1	0.50	1			1					
25	Repair to rain damages on Gunjali Idapanur road and construction of CD near Gunjali village.		1	2.00	1	2.00	1			1					
26	Breach filling at ch. 381 of RDS main canal left side & right side		1	4.00	1	4.00	1		1						
27	Breach filling at ch. 628 RDS main canal right side		1	4.50	1	4.50	1		1						
<b>Total</b>			<b>27</b>	<b>70.80</b>	<b>27</b>	<b>70.80</b>	<b>27</b>	<b>0</b>	<b>12</b>	<b>15</b>					

ಅತಿವೃಷ್ಟಿ/ ಪ್ರವಾಹದಡಿಯಲ್ಲಿ ಅಡಿಯಲ್ಲಿ ಕೈಗೆತ್ತಿಕೊಂಡ ವಿವಿಧ ಇಲಾಖಾ ಕಾಮಗಾರಿಗಳ ವಿವರಗಳ ಮಾಹಿತಿ

**ತಾಲೂಕು: ಮಾನವಿ ಇಲಾಖೆ: ಜಲ ಸಂಪನ್ಮೂಲ ಇಲಾಖೆ ( no 5 Canal Division Yermarus camp )**

1	Distributory -95 in Km. 0.00 to 5.00 Rising of bank and filling of rain cuts and scour filling	1	3.00	1	3.00	1			1					
2	Distributory -95 in Km. 5.00 to 7.00 Rising of bank and filling of rain cuts and scour filling	1	2.00	1	2.00	1			1					
3	Distributory -98 in Km. 5.00 to 8.00 Rising of bank and filling of rain cuts and scour filling	1	2.00	1	2.00	1		1						
4	Distributory -98 in Km. 8.00 to 12.00 Rising of bank and filling of rain cuts and scour filling	1	2.00	1	2.00	1		1						
5	Distributory -98 in Km. 12.00 to 15.00 Rising of bank and filling of rain cuts and scour filling	1	2.00	1	2.00	1			1					
6	Distributory -98 in sub dusy-98/3L Rising of bank and filling of rain cuts and scour filling	1	2.00	1	2.00	1		1						
7	Distributory -98 in sub dusy-98/4L Rising of bank and filling of rain cuts and scour filling	1	2.00	1	2.00	1			1					
8	Distributory -98 in sub dusy-98/5L Rising of bank and filling of rain cuts and scour filling	1	2.00	1	2.00	1			1					
9	Rising of bank and filling of rain cuts in Gorkal tank	1	2.50	1	2.50	1			1					
10	Reconstruction of damaged flood bank to Kallur Anicut	1	8.45	1	8.45	1			1					
11	Desilting of Vijayanagara Canal Km 1.00	1	1.40	1	1.40	1			1					
12	Desilting of Vijayanagara Canal Km 2.00	1	1.00	1	1.00	1			1					
13	Desilting of Vijayanagara Canal Km 3.00	1	1.00	1	1.00	1			1					
14	Filling of Ruts and pits and spreading of Murrum & Impruments to Shoulders and removal of jungle from Kallur to Kalmala Aycut Road	1	5.00	1	5.00	1			1					
15	Restoration of Ayacut Road From Kallur to Dinni	1	2.00	1	2.00	1			1					

16	Reconstruction of damaged canal bunds in ch. 180 to 203 including breach filling at ch. 203 to 204 left side of RDS main canal		1	12.85	1	12.85	1		1						
17	Reconstruction of damaged canal bunds in ch. 204 to 211 including breach filling at ch. 204 to 205 right side of RDS main canal		1	6.00	1	6.00	1		1						
18	Resectioning in Dist. 98 from km 4.40 to 11.52		1	3.00	1	3.00	1			1					
Total			18	60.20	18	60.20	18	0	5	13					